

Antioxidant

| Flux | Characteristics and Uses |
|------|---|
| T-55 | Antioxidant for brazing iron, stainless, copper alloy and others. There remains scale on surface after brazing and so washing surface is needed. |